

93/95/97 50MHz SCOPEMETER

USERS MANUAL

Philips 4822 872 00496
 Fluke 916119
 920120



CONTENTS

CONTENTS		page			
1	OPERATOR SAFETY	1-1	6.1	Measuring voltage (AC/DC)	6-1
1.1	Attention	1-1	6.2	Measuring resistance	6-2
1.2	Introduction	1-1	6.3	Testing diodes	6-3
1.3	Safety precautions	1-1	6.4	Continuity testing	6-4
1.4	Caution and warning statements	1-1	6.5	Using the scope trace display in the meter mode	6-5
1.5	Symbols	1-1	6.6	Measuring the frequency of a sine wave signal	6-6
1.6	Impaired safety-protection	1-1	6.7	Looking at the details	6-7
2	GETTING STARTED QUICKLY	2-1	6.8	Using the printer (Model 97)	6-8
2.1	General	2-1	7	OPERATION VERIFICATION PROCEDURE	7-1
2.2	Contrast adjustment of the display	2-1	7.1	General information	7-1
2.3	Quick scope operation via channel A (RED)	2-2	7.2	How to enter the operation verification	7-1
2.4	Quick multimeter operation channel A (RED)	2-3	8	PREVENTIVE MAINTENANCE	8-1
2.5	Quick signal generator operation (Model 97)	2-4	8.1	Maintenance	8-1
3	QUICK OPERATION	3-1	8.2	Preventive maintenance	8-1
3.1	General	3-1	8.3	Calibration	8-1
3.2	ScopeMeter	3-1	8.4	Battery replacement	8-1
3.3	Meter	3-3	8.5	Fuse replacement	8-2
3.4	Scope	3-7	8.6	Service	8-2
3.5	Scope model 95, 97	3-10	9	REPLACEMENT PARTS	9-1
3.6	Scope model 97	3-12	10	SPECIFICATIONS	10-1
3.7	Useful tips	3-15	10.1	Introduction	10-1
4	INSTALLATION INSTRUCTIONS	4-1	10.2	Display	10-1
4.1	Power supply	4-1	10.3	Oscilloscope	10-1
4.2	Stand-up and holster	4-2	10.4	Multimeter	10-4
4.3	Probe adjustment and calibration	4-3	10.5	Generator	10-5
5	SCOPEMETER FUNCTIONS	5-1	10.6	Undo	10-5
5.1	ScopeMeter	5-1	10.7	Input terminals	10-5
5.2	Meter	5-1	10.8	External power requirements	10-5
5.3	Scope	5-8	10.9	Internal batteries	10-5
5.4	Scope Models 95, 97	5-13	10.10	Environmental data	10-6
5.5	Scope Model 97	5-15	10.11	Mechanical data	10-6
5.6	Power on and Liquid Crystal Display	5-19	10.12	Accessories	10-6
6	APPLICATIONS	6-1	11	Sales and Service all over the world	11-1
			12	Index	12-1